Itemized Receipt

Date paid:

Receipt# 0001

RECEIVED FROM

FROM

PAYMENT

Paid by Credit card

Card ending 4242

DESCRIPTION	QTY	RATE	AMOUNT
Labor: kitchen faucet replacement Remove old faucet, install and test	2	$85.00	$170.00
Kitchen faucet Pull-down, stainless	1	$189.00	$189.00
Braided supply lines Pair, 20 in	1	$18.50	$18.50
Trip charge	1	$45.00	$45.00

Subtotal		$422.50
Sales tax	8.25 %	$34.86
Total		$457.36

AMOUNT PAID $457.36

Balance due $0.00

NOTES

Thank you for your payment! Parts carry the manufacturer's warranty; labor is guaranteed for 90 days.

Created with Onigiri — onigiri.one