

P/N	S/N	Key P/N,S/N	Keyword	Condition	Tag Details	Quantity
018804-000	0905200028483	018804-000,0905200028483	BATTERY	SPECTED/TESTE	FRA FORM 1 SABENA TECHNICS DNR 12 FEB 202	1
018804-000	0905200167508	018804-000,0905200167508	BATTERY	OVH	EASA SINGLE SABENA TECHNICS DNR 01 AVR 20	1
018804-000	122031	018804-000,122031	BATTERY	OVH	EASA SINGLE SABENA TECHNICS DNR 18 AVR 20	1
021121-11	63	021121-11,63	HORIZONTAL STABILIZER ACTUATOR	REPAIRED	FAA DUAL AEROPRECISION REPAIR & OVERHAUL	1
021127	72	021127,72	ACTUATOR EMER AIL TRIM ASSY	INSPECTED	FAA DUAL AEROPRECISION REPAIR & OVERHAUL	1
021137-16	191	021137-16,191	LEFT/RIGHT INBOARD FLAP ACTUAT	AS REMOVED		1
021137-16	285	021137-16,285	LEFT/RIGHT INBOARD FLAP ACTUAT	AS REMOVED		1
021137-16	804	021137-16,804	LEFT/RIGHT INBOARD FLAP ACTUAT	REPAIRED	FAA DUAL AEROPRECISION REPAIR & OVERHAUL	1
105034-07	639	105034-07,639	ELEVATOR ARTIFICIAL FEEL UNIT	REPAIRED	FAA DUAL AERO PRECISION REPAIR 03 JAN 2021	1
105045-06	1811	105045-06,1811	AILERON AUX AFU	REPAIRED	FAA DUAL AERO PRECISION REPAIR 25 NOV 2015	1
105045-06	2101	105045-06,2101	AILERON AUX AFU	REPAIRED	FAA DUAL AERO PRECISION REPAIR 10 JUL 2017	1
106043-19	2153	106043-19,2153	ELEV ARTHUR Q-UNIT	REPAIRED	EASA DUAL DASSAULT 12 FEB 2020	1
106788A185	SNT150226	106788A185,SNT150226	ACTUATOR	OVH	FAA DUAL CONSOLIDATED A/C SUPPLY 26 FEB	1
12-337-33	266	12-337-33,266	SELECTOR LANDING GEAR	REPAIRED	FAA DUAL INTERSKY PRECISION 16 JUL 2020	1
150T378	1085	150T378,1085	THERMOSTAT	INSPECTED	FAA DUAL CONSOLIDATED A/C SUPPLY 06 APR	1
150T378	1446	150T378,1446	THERMOSTAT	INSPECTED	FAA DUAL CONSOLIDATED A/C SUPPLY 08 MAR	1
1780-00-1	1504	1780-00-1,1504	VALVE	REPAIRED	FAA DUAL AEROCNTROLEX GROUP 26 JAN 20	1
2020A003	106	2020A003,106	INITIATOR	REPAIRED	COFC ALKAN 12 JUN 2014	1
2095A010400	127	2095A010400,127	OUTFLOW VALVE	REPAIRED	EASA SINGL LIEBHERR 02 JUL 2019	1
2096E010500	677	2096E010500,677	PNEUMATIC OUTFLOW VALVE	REPAIRED	EASA SINGLE LIEBHERR 20 APR 2018	1
2096Z020500	674	2096Z020500,674	Soupape pneumatique 45 000 ft	SPECTED/TESTE	EASA SINGLE LIEBHERR 15 OCT 2018	1
22201D141701	508	22201D141701,508	Sûlcteur prÚssu F50	SPECTED/TESTE	EASA SINGLE LIEBHERR 19 JUN 2020	1
22201N071001	01141	22201N071001,01141	PRESSU CONTROLLER	SPECTED/TESTE	EASA DUAL LIEBHERR 11 OCT 2019	1
22201N071001	01148	22201N071001,01148	PRESSU CONTROLLER	SPECTED/TESTE	EASA DUAL LIEBHERR 23 JUN 2020	1
2396-323-0	1938	2396-323-0,1938	DC AMMETER	SPECTED/TESTE	EASA DUAL THALES AVS 15 JUL 2020	1
2415-1010	1599	2415-1010,1599	VALVE BOX	OVH	FAA DUAL CONSOLIDATED A/C SUPPLY 22 JUN	1
2415-1010	1857	2415-1010,1857	VALVE BOX	OVH	FAA DUAL CONSOLIDATED A/C SUPPLY 17 APR 2	1
2415-1010	1936	2415-1010,1936	VALVE BOX	OVH	FAA DUAL CONSOLIDATED A/C SUPPLY 10 JUL 2	1
2-4414-2	SNT200035	2-4414-2,SNT200035	Transmetteur	REPAIRED	EASA DUAL SAFRAN ELECTRONICS & DEFENSE I	1
2606881-201	11967	2606881-201,11967	FAN AHC	INSPECTED	FAA DUAL HONEYWELL INTERNATIONAL 10 AUG	1
2725F030100	01155	2725F030100,01155	CABIN AIR CONDITIONING FLOW LI	OVH	EASA DUAL LIEBHERR 12 MAY 2020	1
2725F030100	740	2725F030100,740	CABIN AIR CONDITIONING FLOW LI	OVH	EASA DUAL LIEBHERR 12 MAY 2020	1
30-1191-5	1211	30-1191-5,1211	Feu de navigation	NEW	FAA DASSAULT 13 DEC 2012	1
30-1191-5	1211L	30-1191-5,1211L	Feu de navigation	NEW	FAA DASSAULT 13 DEC 2012	1
3070685-6	SNT170188	3070685-6,SNT170188	PCD LIMITER	REPAIRED	FAA DUAL HONEYWELL INTERNATIONAL 08 SEP	1
3070964-2	17-150262-43983	3070964-2,17-150262-43983	HARNES	NEW	FAA HONEYWELL INTERNATIONAL 24 JAN 2017	1
3073914-4	96465110	3073914-4,96465110	Ignition unit	OVH	FAA DUAL AIRLINE COMPONENT PARTS LLC 04	1
3073914-4	970218000044	3073914-4,970218000044	Ignition unit	OVH	FAA DUAL AIRLINE COMPONENT PARTS LLC 13	1
3213902-2	432	3213902-2,432	PRESSURE REGULATING VALVE	OVH	FAA DUAL AIRMARK COMPONENTS 19 JAN 2021	1
3213902-2	P-219	3213902-2,P-219	PRESSURE REGULATING VALVE	REPAIRED	FAA DUAL AIRMARK COMPONENTS 21 APR 2021	1
3830061-2	2397	3830061-2,2397	FUEL NOZZLE APU	OVH	FAA DUAL DELAVAN INC 19 JAN 2021	1
4011287	5351	4011287,5351	WINDSHIELD WIPER MOTOR	INSPECTED	FAA DUAL CONSOLIDATED AIRCRAFT SUPPLY 16	1
4011287	6365	4011287,6365	WINDSHIELD WIPER MOTOR	REPAIRED	FAA DUAL CONSOLIDATED AIRCRAFT SUPPLY 01	1
405-20403-13200	020	405-20403-13200,020	COUPLER HALF,QUICK DISC COUPLG	AS REMOVED	SERVICEABLE TAG DATED 23 FEB 2021	1
4863-559-80-10	395	4863-559-80-10,395	TRIPLE TRIM POS INDICATOR	REPAIRED	FAA DUAL PACIFIC SOUTHWEST INST 06 FEB 20	1
597-2091-055	445	597-2091-055,445	CONTROL BOX	AS REMOVED		1
6002614-3	MAY81-128	6002614-3,MAY81-128	Ampli anti-skid	SPECTED/TESTE	EASA SINGLE AAR 23 JUN 2008	1
60909-1	7988	60909-1,7988	ACCUMULATEUR	OVH	FAA DUAL CONSOLIDATED A/C SUPPLY 10 DEC	1
622-2552-001	416	622-2552-001,416	HF COUPLEUR	REPAIRED	EASA DUAL ROCKWELL COLLINS 23 MAR 2020	1
665054EE2004	09-08	665054EE2004,09-08	ENGINE FUEL SUPPLY HOSE	NEW	EASA DASSAULT 24 JAN 2014	1
665054EE2004	09-08	665054EE2004,09-08	ENGINE FUEL SUPPLY HOSE	NEW	EASA DASSAULT 24 JAN 2014	1
683T504Y01SE	200	683T504Y01SE,200	CONTROL BOX APU	REPAIRED	FAA DUAL MIDWAY AEROSPACE 02 MAY 2017	1
683T504Y02SE	252	683T504Y02SE,252	CONTROL BOX APU	REPAIRED	EASA DUAL ZODIAC AERO ELECTRIC 06 OCT 20	1
70080042-2	337931440	70080042-2,337931440	FAN INLET HOUSING	OVH	FAA DUAL HONEYWELL INTERNATIONAL 06 FEB	1
7021-000	19	7021-000,19	NOSE CONE PRESSURE REGULATION	OVH	FAA DUAL CONSOLIDATED AIRCRAFT SUPPLY 21	1
706720-1	211	706720-1,211	AMPLIFICATEUR JAUGEUR	SPECTED/TESTE	EASA DUAL ZODIAC AEROTECHNICS 28 DEC 20	1
716-686	254	716-686,254	FUEL QUANTITY INDICATOR	SPECTED/TESTE	EASA DUAL ZODIAC AEROTECHNICS 23 JAN 20	1
716-686	326	716-686,326	FUEL QUANTITY INDICATOR	SPECTED/TESTE	EASA DUAL SAFRAN AEROTECHNICS 23 JUN	1
792367-2	1657	792367-2,1657	GAUGE FUEL	NEW	EASA DASSAULT 01 SEP 2015	1
822-0273-002	3V7HJ	822-0273-002,3V7HJ	REVERSIONARY SWITCHING PANEL	REPAIRED	FAA DUAL ROCKWELL COLLINS 06 NOV 2020	1
822-0385-002	3FFBH	822-0385-002,3FFBH	AUTOPILOT CONTROL PANEL	REPAIRED	EASA DUAL ROCKWELL COLLINS 30 APR 2021	1
822-0730-334	841	822-0730-334,841	Radio tuning unit	REPAIRED	EASA DUAL ROCKWELL COLLINS 30 NOV 2020	1
822-1075-001	252	822-1075-001,252	DATA ACQUISITION UNIT	SPECTED/TESTE	EASA DUAL ROCKWELL COLLINS 05 MAY 2020	1
90G229	3063	90G229,3063	MANO-CONTACT	MANUFACTUREE	EASA DASSAULT 24 SEP 2004	1
90G229	3065	90G229,3065	MANO-CONTACT	MANUFACTUREE	EASA DASSAULT 24 SEP 2004	1
90G229	3066	90G229,3066	MANO-CONTACT	MANUFACTUREE	EASA DASSAULT 24 SEP 2004	1
990-3333-244	9110057987	990-3333-244,9110057987	BOITIER RADARISTE	REPAIRED	FAA DUAL BAKER ELECTRONICS 05 NOV 2019	1
990-3333-244	99110000961	990-3333-244,99110000961	BOITIER RADARISTE	REPAIRED	FAA DUAL BAKER ELECTRONICS 14 DEC 2020	1
A24519001	FM957	A24519001,FM957	PRESSURE RELIEF VALVE	OVH	FAA DUAL CONSOLIDATED A/C SUPPLY 05 FEB	1
A24522-1	FM335	A24522-1,FM335	EMERGENCY BRAKE VALVE	REPAIRED	SAFRAN LS DNR	1
A24522-1	FM452	A24522-1,FM452	EMERGENCY BRAKE VALVE	REPAIRED	EASA SINGLE SAFRAN LANDING SYSTEM 23 JAN	1
A24523	FM350	A24523,FM350	SHUTTLE VALVE ASSY → C NT00	REPAIRED	FAA DUAL DUNCAN AVIATION 26 FEB 2020	1
A24523	FM360	A24523,FM360	SHUTTLE VALVE ASSY → C NT00	REPAIRED	EASA SINGLE SAFRAN LANDING SYSTEM	1
A24523	FM427	A24523,FM427	SHUTTLE VALVE ASSY → C NT00	REPAIRED	FAA DUAL DUNCAN AVIATION 26 FEB 2020	1
A24523	FM727	A24523,FM727	SHUTTLE VALVE ASSY → C NT00	REPAIRED	FAA DUAL DUNCAN AVIATION 15 JUL 2015	1
A24523	FM730	A24523,FM730	SHUTTLE VALVE ASSY → C NT00	INSPECTED	FAA DUAL DUNCAN AVIATION 07 JUL 2015	1
AV19A1061	L12210	AV19A1061,L12210	VALVE PRESSURE REDUCING	REPAIRED	FAA DUAL CONSOLIDATED A/C SUPPLY 31 MAR	1
AV23C1101	L68253	AV23C1101,L68253	STBY PUMP SELECTOR VALVE	REPAIRED	FAA DUAL DUNCAN AVIATION 01 AUG 2018	1
B06GA1051-1	858	B06GA1051-1,858	PRESSURE REDUCING VALVE	REPAIRED	EASA SINGLE GOODRICH ACTUATION SYSTEMS 1	1
B14DE2031	317	B14DE2031,317	FEED TANK PR RED VAL	REPAIRED	EASA DUAL GOODRICH ACTUATION SYSTEMS 2	1
B14DE2041	24	B14DE2041,24	DETENDEUR CARBURANT	REPAIRED	EASA DUAL GOODRICH ACTUATION SYSTEMS 0	1
B45CB1042	221	B45CB1042,221	ENGINE ARTICULATED PIPE	REPAIRED	EASA DUAL LIEBHERR 17 JUL 2020	1
B45CB1072	90	B45CB1072,90	ENGINE ARTICULATED PIPE	OVH	EASA DUAL LIEBHERR 17 FEB 2020	1
B97M31-201	H08264	B97M31-201,H08264	Robinet d isolement	NEW	EASA DASSAULT 15 OCT 2015	1
BYLBS2642	434	BYLBS2642,434	ANTI ICING VALVE	REPAIRED	43416 GE AVIATION 12 NOV 2018	1
C23843-10-1	B90	C23843-10-1,B90	DETECTION BOX	REPAIRED	EASA SINGLE SAFRAN LANDING SYSTEMS 06 SE	1
C23844-11	U245	C23844-11,U245	DETECTION BOX	REPAIRED	EASA SINGLE SAFRAN LANDING SYSTEMS 23 DI	1
C23926-1102	U54	C23926-1102,U54	ACTUATING CYLINDER	AS REMOVED		1
C24244-0-2	U50	C24244-0-2,U50	UPLCK BOX	REPAIRED	EASA DUAL SAFRAN LANDING SYS 087 DEC 201	1
C24245-0-2	U64	C24245-0-2,U64	UPLCK BOX	REPAIRED	EASA SINGLE SAFRAN LANDING SYSTEM 02 JAN	1
C24245-4-2	U109	C24245-4-2,U109	UPLCK BOX	REPAIRED	EASA SINGLE SAFRAN LANDING SYSTEM 10 JUN	1
C24370-202	B1221	C24370-202,B1221	RESTRICTOR	REPAIRED	EASA SINGLE SAFRAN HYDREP 19 MAY 2015	1
C41B30213-39	RW88-02C	C41B30213-39,RW88-02C	THRUST REVERSER DOOR	REPAIRED	FAA DUAL TRIUMPH 29 JUN 2018	1
C41B30213-39	RW89-11C	C41B30213-39,RW89-11C	THRUST REVERSER DOOR	REPAIRED	FAA DUAL TRIUMPH 25 MAY 2016	1
CH8066093732N00	M600460-013	CH8066093732N00,M600460-013	FILTER	SPECTED/TESTE	EASA SINGLE SABENA TECHNICS DNR 06 AVR 2	1
CI816B	492	CI816B,492	C.I.	REPAIRED	FAA DUAL INTERSKY PRECISION 12 DEC 2017	1
CI819A	75	CI819A,75	CI	REPAIRED	FAA DUAL INTERSKY PRECISION INSTRUMENTS	1
CI820B	828	CI820B,828	CIRCUIT PRINTED	MANUFACTUREE	EASA DASSAULT 01 DEC 2016	1
CI821A	628	CI821A,628	C.I.	NEW	EASA DASSAULT 19 APR 2018	1
CI823B	1039	CI823B,1039	LANDING GEAR CIRCUIT BOARD	TESTED	FAA DUAL INTERSKY PRECISION INSTRUMENTS	1
CI823B	1180	CI823B,1180	LANDING GEAR CIRCUIT BOARD	TESTED	FAA DUAL INTERSKY PRECISION INSTRUMENTS	1
CI823B	24	CI823B,24	LANDING GEAR CIRCUIT BOARD	REPAIRED	FAA DUAL INTERSKY PRECISION INSTRUMENTS	1
CI999-1	778	CI999-1,778	DE-ICING CARD	NEW	EASA DASSAULT 29 NOV 2018	1
CI999-1	794	CI999-1,794	DE-ICING CARD	REPAIRED	FAA DUAL INTERSKY PRECISION 09 FEB 2018	1
CN100	2185	CN100,2185	SHUTTLE VALVE ASSY	NEW	EASA FORM ONE DASSAULT 14 APR 2015	1
CYLBS0419	382	CYLBS0419,382	VALVE CHECK	REPAIRED	FAA DUAL GE AVIATION 06 MAR 2018	1
CYLBS0419	413	CYLBS0419,413	VALVE CHECK	REPAIRED	FAA DUAL GE AVIATION 22 DEC 2020	1
D22073-3	B294	D22073-3,B294	DETECTION BOX	REPAIRED	EASA SINGL SAFRAN LANDING SYS 22 JUL 2021	1
D22073-3	U7	D22073-3,U7	DETECTION BOX	REPAIRED	EASA SINGL SAFRAN LANDING SYS 01 JUL 2020	1
F50B297A4	CN037	F50B297A4,CN037	DOOR ENGINEER ASSY	AS REMOVED		1
F50B58-185000	35AT189	F50B58-185000,35AT189	JET PIPE	AS REMOVED		1
F50B621810A2	136	F50B621810A2,136	CTRL BOX ASSY	REPAIRED	EASA SINGLE SAFRAN ELECTRICAL POWER 09 S	1
FE964	317	FE964,317	CIRCUIT IMPRIME	SPECTED/TESTE	EASA DUAL ESTERLINE 04 APR 2019	1
P600365RD	SNT210094	P600365RD,SNT210094	FLASQUE AVANT REP DALLIC	REPAIRED	EASA DUAL SABENA TECHNICS DNR 09 JUL 202	1