





TECH STACK

RealWear assisted reality wearable devices should be charged with
sufficient battery for expected duration of the call (spare battery available
for hot swap if required)

- Internet connection established & tested to confirm bandwidth is sufficient to support the call with selected approved/optimized app software solution
- Remote collaboration solution tested, including the ability to collaborate with guests outside corporate network (if needed)
- Headphones/bluetooth speaker available, paired and set-up, if required



PLANNING & RISK ASSESSMENT

- Site-based risk assessment conducted to confirm all PPE and other safety requirements, exclusion zones & risk controls in place for all identified risks
- RealWear devices fitted correctly to users: display pod situated under line of sight of the dominant eye, HMT fitted securely to selected head-mounting option, all other PPE unencumbered. We recommend our RealWear Academy 101 course. Contact academy@realwear.com
- Approval received from all stakeholders to record site activities /conversations with video/still images
- Safety spotter nominated to observe for hazards during first-time use or as required in accordance with risk assessment



WORK SITE ENGAGEMENT

- Site Leadership briefed on the remote collaboration activity with clear obtained approval to conduct image/video recording
- Camera permit in place, if required
- All personnel involved in the activity have been fully briefed on the use of live video and/or recording
- STOP work authority in place

Once you have all the necessary communications, approvals, tools and safety assessments in place, mark them completed in the checklist.

Happy collaborating!

